



Enabling Your Ideas

Technical Document

15L Slant-PRO Lathe Light Installation

Product Identification: Lathe Light Kit (PN 35685)

Purpose: This document details installation of the Lathe Light Kit in the 15L Slant-PRO lathe enclosure.

Qty.	Lathe Light Kit (PN 35685)	PN
1	Lathe Light w/bracket	35428
4	10-32x7/16" Pan Head Screw	32071
3	Wire Ties	32791

NOTE: If any of these items are missing, contact Tormach Customer Service at (608) 849-8381 for a replacement.



1. Attach Lathe Light w/bracket to lathe enclosure ceiling using four 10-32x7/16" Pan Head Screws (see **Figure 1**); holes are pre-threaded.

2. Route light cord along Limit Switch Cables, around back and through lathe casting location shown in **Figure 2**.

3. Secure cord to cables with Wire Ties (see **Figure 2**).

4. Connect to 115 VAC power outlet.




Figure 1




Figure 2